

Engineering Report

BeSure Fire & Security
Cirket House
Sidney Little Road
St Leonards on Sea
East Sussex
TN38 9PU
01424 852343

enquiries@besurefireandsecurity.com

Site Name	Hendy Group Ltd - Lottbridge Drove	Site ID	06530
Address	18, 20-22 Lottbridge Drove Eastbourne East Sussex BN23 6NS		Hendy Group Ltd Purchase Ledger School Lane Chandlers Ford Eastleigh, Hampshire SO53 4DG
Contact	Kam Bamrah	Customer Reference	B1033
System Type	Emergency Lighting		
Call No.	227082	Type	Preventative Maintenance
		Reason	Preventative Maintenance

Description Call Remarks: Account No. HL0007
Eng note switches for rear top floor offices are in comms cupboard at end of corridor
Preventative Maintenance : Emergency Lighting
Notes : To Invoice
Maintenance appt booked for 12.11.24 AM Anytime
----- GILL: 13/09/24 @ 11:43 -----

Started 12/11/24 @ 08:45:00 **Finished** 12/11/24 @ 10:41:00 **Travel Time** 00:01:00

Remarks Carried out full service of EMLS.

1x fail please see attachments for picture and location
fitting failed fixed hung exit sign above Mazda building entrance doesn't have green charging light so possibly
no power at all at fitting

Sales Enquiry 31169

Checklist

<u>Check Item</u>	<u>Checked ?</u>	<u>Remarks</u>
Non-Maintained Emergency Light Tested	Yes	tested and working other than 1 x fixed hung exit sign photo and location in attachments
Maintained Emergency Light Tested	Yes	tested and working
Combined Emergency Lights	Yes	tested and working
Ensure that all 'Test Switches' have been left in the correct position	Yes	checked
Log Book Updated	Yes	updated and signed

Risk Assessment

<u>Check Item</u>	<u>Checked ?</u>	<u>Remarks</u>
-------------------	------------------	----------------

Customer Signature

Engineer

Richard Brady

Name