

<b>JOB #</b>	10972
<b>DATE</b>	11th April 2024
<b>CLIENT</b>	The Hendy Group
<b>SITE ADDRESS</b>	20-22 Lottbridge Drive, Eastbourne, East Sussex BN23 6NS
<b>ISSUE REPORTED</b>	<p>Carry out service at Eastbourne Powrmatic OUH60 - SN 06017L384954</p> <p>ANDY - OFTEC SHEET NEEDS DOING</p> <ul style="list-style-type: none"> <li>- Service Units</li> <li>- Complete Job Sheet</li> <li>- Complete Gas Safe</li> <li>- Attach Gas Analyser Reports</li> <li>- Customer Sign Jobs</li> </ul>

WORK CARRIED OUT	CALL BACK REQUIRED?
<p>Attend site to carry out routine service of the oil fired heater.</p> <p>Heater fully serviced and tested with no issues found. FGA readings are ok and flue flow test passed. Left heater in working order.</p>	No

FURTHER ACTION & MAT.REQUIRED	MATERIALS USED
None	None

APPLIANCE DETAILS	ANALYSER PHOTO (If applicable)
Powrmatic OUH60/F/1 - s/no. O6017L384954	

ENGINEERS TIME ON SITE (hrs)	MILEAGE
3 0	92

CUSTOMER NAME	CUSTOMER SIGNATURE
Dave Jenkins	